REFERENCES

Ref: CM-RW-Camrail

EN 09/02/2012

1/1

www.zinga.eu

RAILWAY BOGIE - CAMRAIL - CAMEROON

Part of a railway sparkling plug has been protected with **ZINGA**.

<u>Problem:</u> agressivity due to urine of passengers







System: Surface preparation: HP cleaning Sandblasting SA 2,5 $Rz = 114 - 50 = 64 \mu m$ ZINGA 3 x 60 μm DFT

